

















30min








1





<p>A1</p>  <p>X1</p>	<p>A2</p>  <p>X1</p>	<p>A3</p>  <p>X1</p>	<p>A4</p>  <p>X2</p>
<p>A5</p>  <p>X1</p>	<p>A6</p>  <p>X4</p>	<p>A7</p>  <p>X4</p>	<p>A8</p>  <p>X2</p>
<p>A9</p>  <p>X2</p>	<p>A10</p>  <p>X2</p>	<p>A11</p>  <p>X2</p>	<p>A</p>  <p>X28</p>
<p>B</p>  <p>X22</p>	<p>C</p>  <p>X28</p>	<p>D</p>  <p>Ø6*18mm/x4</p>	<p>E</p>  <p>M6*25mm/x4</p>
<p>F</p>  <p>M5*14mm/x48</p>	<p>G</p>  <p>M5/x16</p>	<p>H</p>  <p>X8</p>	<p>I</p>  <p>X4</p>
<p>J</p>  <p>X16</p>	<p>K</p>  <p>X1</p>	<p>3/10</p>	


Step.1

A  X12	B  X8	K  X1
A2  X1	A3  X1	A5  X1







Step.2




A8  X2	A  X6	B  X4	K  X1
---	--	--	--



Step.3



Step.4




Step.5

A4




X2

C




X4


K



X1



Step.6








A6






X4







Step.7









Step.8







Step.9





Step.10



Step.11




Step.12




Step.13

A7



x4



Step.14

J




x16

F



M5*14mm/x16

K



X1

